

HARPER COUNTY ROAD & BRIDGE
Weekly County Commission Report
March 21-25, 2016

KENT STONEBRAKER-EAST FOREMAN

1. Replaced damaged running boards at Bridge's 694-23 & 666-15. Dozer 627 ripping shale at Plumb Thicket Landfill. Graders patrolling.
2. Excavator 635 removing trees & cleaning creek channel around Bridge 668-23. Excavator 635 loading up trees and brush from ditch on Rd 672-22 on Truck 216. Truck 216 hauling brush & trees from ditch on Rd 672-22 to Harper County Landfill. Truck 305 hauling shale to soft spots on Rd's 706-23 & 24. Grader 259 spreading shale on Rd's 706-23 & 24. Dozer 627 ripping shale at Plumb Thicket Landfill. Graders patrolling.
3. Excavator 635 loading up trees & brush from ditch on Rd 672-22 on Truck 216. Truck 216 hauling off trees & brush from ditch on Rd 672-22 to Harper County Landfill. Truck 305 hauling shale to Rd 704-25. Grader 259 spreading shale on Rd 704-25. Dozer 627 ripping shale at the Wencil Pit. Graders patrolling.
4. Excavator 635 removing trees in ditch along Rd 741-B. Dozer 627 ripping shale at the Wencil Pit. Trucks 216 & 305 hauling shale to Rd 704-25. Grader 259 spreading shale on Rd 704-25. Graders patrolling.
5. Dozer 627 ripping shale at the Wencil Pit. Graders patrolling. Truck 216 hauling shale to Rd's 704-25 & 26. Grader 259 spreading shale on Rd's 704-25 & 26.

JIM THOMPSON-SHOP FOREMAN

1. #310 2006 Sterling Truck, removed rear driveline for repairs.
2. DOA 2011 Dodge, service job-158,743 miles. #500 2012 Chevrolet Pickup, service job-64,784. #149 JD 6605, service call-won't start.
3. #118 2006 Sterling Truck, replaced batteries. #149 JD 6605, service job, repairs to steering column & miscellaneous repairs for mowing season.
4. Noxious Weed 2011 Ford, service job-34,475 miles. Noxious Weed 2005 Ford, service job-62,964 miles. #251 JD 6115D, looked over for mowing season.
5. Noxious Weed, 2015 Dodge #1, service job. Noxious Weed 2015 Dodge #2, service job-4,358 miles. #251 JD 6115D, repairs for mowing season.

LAWRENCE SMITH-WEST FOREMAN

Fixed holes & soft spots from heavy oil field traffic with shale on Rd's 721-Y, 710-7, 704-9, 712-7 & 8 & 713-V. Ripped & stockpiled shale at the Stark Pit. Dozer 628 & Loader 122 pushing soil over used pit area. Sanded Rd's 712-8 & 9. Excavator 632 helping Bridge Crew backfill at Bridge 674-9 #2. Graders patrolling. spreading shale & sand & doing some ditch work. Fixed truck tires. Fixed hole on Corwin Rd 715-V with gyp.

JEFF NULIK-BRIDGE FOREMAN

1. Tie stringer together at pier on Bridge 674-9 #2. Installed wing wall walers & 12" channel on tops of wing wall piling.
2. Drove sheet piling at Bridge 674-9 #2.
3. Installed angle iron over sheet piling at Bridge 674-9 #2. Installed 17 new decking boards.
4. Completed welding & backfill At Bridge 674-9 #2. Installed hub rails & re-installed guardrail & posts.
5. Started crane dismantle. Made temporary patch at Bridge 709-M #1.